Ref #	Hits	Search Query	DBs	Default Operator	Plurals	Time Stamp
L1	3.	super adj corr adj b	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 12:00
L2	55	corrosion adj preventi\$2 adj compound	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 12:00
L3	0.	2 with lektrotech	US-PGPUB, USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 12:01
L4	19	2 same metal	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 12:09
L5	1177	prevent\$4 with crack near1 propagat\$5	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 12:09
L6	2	2 and 5	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 12:10
L7	97904	etch\$4 and clean\$4	US-PGPUB; USPAT; EPO; IPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 12:10
L8	463182	corrosion corros\$4	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 12:10
L9	19	.5 and 7 and 8.	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 12:10
S1	409	metal same etch\$4 same (prevent\$4 near1 corrosi\$4)	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 11:59
S2	347631	(prevent\$4 mitigat\$5 less\$4 decreas\$4 lower\$4 preclud\$4 obviat\$4 deter\$4 protect\$4 relieve abat\$6 diminish\$4 reduc\$5) with (crack propagation pit crevice grain fatigue fracture)	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/15 15:42

S3	10	S1 same S2	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/15 15:50
S4	1	"08276533"	DERWENT	OR	ON	2005/12/15 15:56
S5	110	metal same etch\$4 same (prevent\$4 near1 corrosi\$4).ab.	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 09:37
S6	4	metal same etch\$4 same (prevent\$4 near1 corrosi\$4). clm.	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/15:15:57
S7	110	metal same etch\$4 same (prevent\$4 near1 corrosi\$4).ab.	US-PGPUB; USPAT; EPO; JPO; DERWENT ; IBM_TDB	OR	ON	2005/12/16 09:37